

**QUARTERLY VISUAL STORMWATER INSPECTION**

Instructions: Quarterly inspections should be conducted to document that the provisions of the SWMP are being followed, and to identify areas needing improvement. The completed forms should be placed in Appendix C, and kept for at least 5 years.

Date: 3/16

Time: 9:40 AM

Weather Conditions: Rainy

	BASIN 1 (PORTION OF BUILDING, FORESTRY STORAGE, SOUTHERN OUTSIDE STORAGE, REFUSE AND RECYCLING CONTAINERS, AND ASPHALT DRIVES)	BASIN 2 (PORTION OF BUILDING, SOUTHERN OUTSIDE STORAGE, ASTS AND DISPENSERS, AND ASPHALT DRIVES)
Any signs of oil sheens, foam, sludge, or rust precipitation?	NO	NO
Any signs of other contaminants at the storage locations or along stormwater flow path?	NO	NO
Observe stormwater flow paths. Any yard waste storage in flow path?	NO	NO
Any litter or trash on ground/rooftop:	NO	NO
Other observations?		



A tyco International Ltd. Company


**SI Water Management Plan**  
**Parks and Recreation Department Main Building**  
 City of Appleton, Wisconsin

Report

AREAS	BASIN 3 (EASTERN GRASS BERM)	BASIN 4 (PORTION OF BUILDING, LOADING DOCK, AND GRASS AREAS)
Any signs of oil sheens, foam, sludge, or rust precipitation?	NO	NO.
Any signs of other contaminants at the storage locations or along storm water flow path?	NO	NO
Observe stormwater flow paths. Any yard waste storage in flow path?	NO	NO
Any litter or trash on ground:	Some	NO
Other observations?		

Inspected by:

 (Signature)  
 Cameron Smith (Printed Name)



A tyco International Ltd. Company